

FIG. 1




FIG.2




FIG.3




FIG.4




FIG.5




FIG.6 (a)




FIG.6 (b)




FIG.7




FIG.8




FIG. 9




FIG.10




FIG.11 (a)





FIG.11 (b)



TORQUE CONVERTER CHARACTERISTIC MAP

FIG.12




FIG.13




FIG.16




FIG.14

DRAFTS OF THE COMPUTER PROGRAM




FIG.15




FIG. 17




FIG.18 (a)




FIG.18 (b)




FIG. 19




FIG.20




FIG.21(a)




FIG.21(b)




FIG.21(c)

